



Goodwin's Mills Fire-Rescue

GENERAL ORDER 08-422

Created Date 08-21-08
Effective Date 08-21-08

08-21-08 Captain Dupras,

Subject:
BW Gas meter docking station

Remarks:
The docking station for the new BW gas meters is mounted in the SCBA room. If you need to charge the unit/ calibrate the unit/ or perform a bump test the meter must be left on and placed in the dock with the unit screen facing in. Note: Bump tests will be done during weekly checks by the career staff and calibration will be done every 6 months or if the unit says it needs it. If you just need to charge the unit after use there is no need to push any buttons on the docking station. See Capt. Dupras if you have any questions